

Appendix C Photographic Record

Dairy and Machine House Building - Exterior



Figure C-1. Photograph looking west at the Castle Street façade of the dairy and machine house building.



Figure C-2. Photograph looking southeast at the eastern elevation showing two distinct portions: the eastern offices and the central dairy.



Figure C-3. Photograph looking south at the eastern elevation showing two distinct portions: the central dairy and the western machine house.



Figure C-4. Photograph looking east at the western wall of the machine house showing blocked-in windows.



Figure C-5. A close-up photograph looking east at the western wall of the machine house showing the blocked-in windows.



Figure C-6. Distinct dog-legged wall of the former shared wall between what was once the cellar (presently referred to as the dairy building) and the mill.



Figure C-7. Photograph looking east at the former doorway or window arch located on the shared wall between what was once the cellar (presently referred to as the dairy building) and mill.



Figure C-8. Photograph looking east at second floor of the dairy and machine house building.



Figure C-9. Photograph looking north at partition wall with two blocked windows and the bottom of the stairwell leading from the partitioned area to the first floor.




Figure C-10. Photograph looking east at the partitioned area at the east end of the dairy and machine house building.



Figure C-11. Photograph of penny tiles encountered in the east office end of the dairy and machine house building.




Figure C-12. Photograph showing the suspended screen visible in the 1966 plans above the stairwell to the second floor.




Figure C-13. Photograph looking south on ground floor of the dairy building at location of first former staircase. A landing is visible half-way up.



Figure C-14. Photograph looking south on ground floor of the dairy building at possible joist insertion points. These are at the same height as the first former staircase landing and possibly indicate there was a mezzanine floor at this height.




Figure C-15. Photograph looking west on ground floor of the dairy and machine house building at location of second former staircase visible in 1959 plans.



Figure C-16. Photograph looking north at single hung sash window in the office portion of the dairy and machine house building.



Figure C-17. Photograph looking north at multi-pane windows of the dairy central portion of dairy and machine house building.



Figure C-18. Photograph looking west at the ground floor of dairy and machine house building.



Figure C-19. Photograph looking west at the north side of the central dairy portion of the dairy and machine house building.



Figure C-20. Photograph showing penny tiling in the office portion of the dairy and machine house building.



Figure C-21. Photograph showing tiling in the central dairy portion of dairy and machine house building.



Figure C-22. Photograph looking south machine house portion of the dairy and machine house building. The larger cylindrical item to the right is the base of the once 90 ft. concrete chimney



Figure C-23. Photograph looking west at the plastered brick wall of ground floor in the machine house portion of dairy and machine house building.



Figure C-24. Photograph looking east at the Cumberland Street façade of Cadbury World.



Figure C-25. Photograph looking southwest at the eastern and northern wall of former smutters and kiln building. The upper floor was added sometime between 1892 and 1901, while the southern extension of 1901 is visible at the rear. There is one blocked in window on the eastern wall and another on the northern wall.




Figure C-26. Photograph looking southwest at the eastern wall of the former kiln and northern wall of the former mill building. The upper floor was added sometime between 1892 and 1901, while the southern extension of 1901 is visible at the rear. Note the jut into the wall is on the second storey.




Figure C-27. Photograph looking southwest west at the eastern wall of the former kiln and northern wall of the former mill building. The upper floor was added sometime between 1892 and 1901, while the southern extension of 1901 is visible at the rear. Note the jut into the wall is on the second storey.



Figure C-28. Photographs looking northwest at southern internal partition wall on the ground floor of the Cadbury World café. The wall was likely present from 1922. Note the blocked-in doorway on the northern internal wall.



Figure C-29. Photographs looking northeast at the abutment of southern internal partition wall on the ground floor of the Cadbury World café to an earlier external wall to the west.




Figure C-30. Photograph looking west on the ground floor of the Cadbury building. Note the brick remnant of a north-south wall either side of the room. This is likely the original walls of the granary and malt floor building. The opening that they form was present by 1922 and may be associated with the earliest outlay of the building however this is unclear.




Figure C-31. Photograph looking west in the ground floor of the Cadbury World building showing steel beams. Note the windows of the mezzanine floor above the door in the photograph on the left.



Figure C-32. Photograph of interior wall of Cadbury World building that would have originally form the north exterior wall of the pre-1900 kiln. Note the bricked in windows of what was once the mezzanine level.



Figure C-33. Detail photograph of interior wall of Cadbury World building looking northwest that would have originally formed the north exterior wall of the pre-1900 kiln showing an arch above a blocked-in window.



Figure C-34. Detail photograph of interior wall of Cadbury World building that would have originally form the north exterior wall of the pre-1900 kiln showing a possible ground floor partition wall and joist insertion point for the original mezzanine level.



Figure C-35. Blocked in doorway in the former kiln building looking east.



Figure C-36. Blocked in doorway in the former kiln building looking east.



Figure C-37. Blocked in doorway in the former kiln building looking east.




Figure C-38. Blocked in window in the former kiln building looking northeast.



Figure C-39. Photograph looking east at blocked in doorway to the eastern room of the former kiln and smutters room.



Figure C-40. Photograph looking east at blocked in doorway to the eastern room of the former kiln and smutters room.



Figure C-41. Photograph looking east at two blocked in doorways (top) either side of current doorway (bottom) to the eastern room of the former kiln and smutters room.



Figure C-42. Photograph looking south at detail of blocked in doorway of the former kiln building. Note the wood to the left of the doorway



Figure C-43. Photograph looking northwest at blocked in doorway and stepped out portion of the wall into the eastern room of the former kiln building.




Figure C-44. Photograph showing former stairwell in the 1901 southern extension looking west in the western area of the former kiln building.



Figure C-45. Photograph showing former stairwell in the 1901 southern extension looking southwest in the most easterly room of the same building (right)



Figure C-46. Photograph looking west at multi-pane fixed window on the first floor of Cadbury World.



Figure C-47. Photograph looking south at column on second Floor 2 of the Cadbury World building with the 1901 southern extension behind.



Figure C-48. Photograph looking west at roof structure of the southern extension.



Figure C-49. Photograph looking north at the roof framing and the windows of the second-floor north wall of the Cadbury World building associated with the 1901-1915 storey addition. Prior to the 1915-1922 raising of the offices and shop building this would have been an exterior wall.




Figure C-50. Photograph looking north at interior of Cadbury World building showing steel framing added to roof structure and steel columns. Note earlier skylights have been covered.



Figure C-51. Photograph looking east at a blocked in doorway in the second floor of the Cadbury World building, the most easterly room of the former kiln building.



Figure C-52. Photograph looking north (left) at a blocked in window in the second floor of the Cadbury World building, the most easterly room of the former kiln building.



Figure C-53. Photograph of tongue and groove timber underneath concrete of the floor in the 2nd floor of the Cadbury World building.



Figure C-54. Photograph of window on third floor looking east from the confectionary factory of the Cadbury World building.




Figure C-55. Photograph of the confectionary factory of the Cadbury World building on third floor looking west.



Figure C-56. Photograph of the confectionary factory of the Cadbury World building on third floor looking west.

Office Building - Exterior



Figure C-57. Photograph looking east at the Cumberland Street façade of Office Building.



Figure C-58. Photograph looking west at the rear of the office building and 1920s addition to the rear of Cadbury building

Office Building – Interior




Figure C-59. Photograph looking west the rise to the front portion of office building in the 1924 extension of the ground floor.



Figure C-60. Photograph looking north at a former exterior window of the office building (Block 2A) associated with the 1915-1922 third storey addition to the building. This photograph is taken from the later 1922-1927 addition at the rear of the Cadbury World building on the first floor



Figure C-61. Photograph looking south at office portion of Building 1 on first floor.



Figure C-62. Photograph looking northwest at office portion of the office building on the first floor showing Cadbury Joyville sign



Figure C-63. Photograph looking south at office portion of the office building on the first floor.



Figure C-64. Photograph looking southwest at office building on the second floor..



Figure C-65. Photograph looking northeast at office space on the third floor.



Figure C-66. Photograph looking northwest at office portion of the office building showing former exterior windows associated with the 1915 addition to the building. This photograph is taken from the later 1922-1927 addition at the rear of the Cadbury World building on the third floor.



Figure C-67. Photograph of window on third floor looking west facing out from the mansard roof (right).



Figure C-68. Photograph looking west at office corridor on the third floor.

Office Building – Interior




Figure C-69. Photograph looking south at computer boards on third floor.

Chocolate Factory and Garage Building - Exterior



Figure C-70. Photograph looking east at the Cumberland Street façade of the chocolate factory and garage building



Figure C-71. Photograph looking west at the former garage on the ground floor.



Figure C-72. Photograph looking north at chocolate factory and garage building on the first floor.



Figure C-73. Photograph looking north at corridor along chocolate factory and garage building on the first floor.

Chocolate and Biscuit Factory Building - Exterior




Figure C-74. Photograph looking west at the Castle Street façade of the chocolate and biscuit factory.



Figure C-75. Photograph looking north at the southern elevation of the chocolate and biscuit factory.

Chocolate and Biscuit Factory Building - Interior




Figure C-76. Photograph looking east at chocolate and biscuit factory building on the ground floor.




Figure C-77. Photograph looking east at chocolate and biscuit factory building on the second floor.




Figure C-78. Photograph looking west at chocolate and biscuit factory building on the second floor.



Figure C-79. Photograph looking west at third floor cafeteria of chocolate and biscuit factory building.



Figure C-80. Photograph looking east at third floor cafeteria of Building 3 (Block B-C).



Figure C-81. Photograph looking west at third floor lift shaft.



Figure C-83. Photograph looking south at tongue and groove wall lining on the second floor of Building 3 (Block C).



Figure C-82. Photograph looking south at bricked in wall section in Block B-C of Building 3 on the ground floor

Chocolate and Biscuit Factory Building - Interior



Figure C-84. Photograph looking east at decorative window in Building 3 Building 3B-C on the second floor.




Figure C-85. Photograph looking south (left) and east (right) at variant multi-pane window on the second floor of building 3 (Block 3B-C) second floor.

Engineering Workshop, Labs and Office Building - Exterior



Figure C-86. Photograph looking northeast at the Cumberland Street façade of engineering workshop, labs and office building.




Figure C-87. Photograph looking west at overbridge between the engineering workshop, labs and office building (Blocks 4A) and the biscuit and dispatch building (Block 5A).



Figure C-88. Photograph looking east into basement and at mezzanine of engineering workshop, labs and office building from ground level.



Figure C-89. Photograph looking east at basement wall of Building 4 (Block 4A). Note the brick infill and the open window running up into the mezzanine level above.



Figure C-90. Photograph looking east at tongue and groove of mezzanine above basement in engineering workshop, labs and office building.



Figure C-91. Photograph of corridor in engineering workshop, labs and office building looking east on the ground floor.




Figure C-92. Photograph looking northwest at Cadbury tour space in engineering workshop, labs and office building on the first floor.



Figure C-93. Photograph looking west at food testing laboratory in engineering workshop, labs and office building on the first floor.



Figure C-94. Photograph looking west at engineering workshop, labs and office building showing tin wash on second floor.



Figure C-95. Photograph looking west at engineering workshop, labs and office building on the second floor.



Figure C-96. Photograph looking west window of engineering workshop, labs and office building on the first floor.




Figure C-97. Photograph looking northwest at office space in the engineering workshop, labs and office building on the first floor.



Figure C-98. Photograph looking southeast at the Cumberland Street façade of the biscuit and dispatch building.



Figure C-99. Photograph looking southwest at the Castle Street façade of the biscuit and dispatch building.



Figure C-100. Photograph looking northeast at the rear of the biscuit and dispatch building.



Figure C-101. Photograph of drying room in the biscuit and dispatch building (Block 4C) looking west on the ground floor.




Figure C-102. Photograph looking west at ground floor in the biscuit and dispatch building (Block 5A-B).



Figure C-103. Photograph looking northwest at the biscuit and dispatch building (Block 5A-B) on the first floor.



Figure C-104. Photograph looking north at the biscuit and dispatch building (Block 5A) on the first floor.




Figure C-105. Photograph looking east at the second floor of the biscuit and dispatch building (Block 5C)




Figure C-106. Photograph looking south at the second floor of the biscuit and dispatch building (Block 4C)



Figure C-107. Photograph of the biscuit and dispatch building (Block 5C) on the third floor looking west.



Figure C-108. Photograph looking east at the biscuit and dispatch building (Block 5B-C) on the third floor.




Figure C-109. Photograph looking east at fourth floor of the biscuit and dispatch building (Block 5C).



Figure C-110. Photograph looking west at fourth floor of the biscuit and dispatch building (Block 5C).




Figure C-111. Photograph looking east at windows on the second floor of the biscuit and dispatch building (Block 5C)




Figure C-112. Photograph looking southeast at windows on the third floor of the biscuit and dispatch building (Block 5C)



Figure C-113. Photograph looking southeast at central boiler house constructed in the 1940s (Block 4B).




Figure C-114. Photograph looking north at central boiler house constructed in the 1940s (Block 4B).



Figure C-115. Photograph looking northeast at central boiler house extensions in the 1950s and 1960s (Block 4B).



Figure C-116. Photograph looking north at ground floor in central boiler house (Block 4B).



Figure C-117. Photograph looking west at ground floor wall in central boiler house (Block 4B). Note the concrete and steel construction.



Figure C-118. Photograph looking north east at covered in area (Block 4B) to the rear of the dispatch building, possibly once the exterior as features the same brown tiling as seen on Building 4 façades.