
RS14- Jennifer Robinson - FS116

underwined cender Files



Photograph 3: View of scour from flood flow in the creek




Photograph 4: View of scoured area from the creek




## Photographs – 9 Freeman Close, Abbotsford, Dunedin




Photograph 1: View of the scour damage from the top of the slope showing shed in creek



Photograph 2: Similar angle taken during flood event







Council Water & Drainage Services

DUNEDIN CITY

of publishing. The accuracy and completeness of This information is variable. Private assets are typically not mapped. Recent changes may not be reflected. Verify on site before commencing work. For all enquiries phone 03 477 4000.

21/10/2016 11:41:58 AM

PARCEL LINES CAN VARY FROM LEGAL PARCEL BOUNDARES This map is for illustration purposes of and is not accurate to surveying, eng

**DUNEDIN CITY COUNCIL - Approved Building Consent Document** 

2013 Urban and rural photography Jan-February 2013. Dunedin City Council CC 8Y 3.0 NZ.