



297 Tomahawk Rd
 There is no open drain, the DCC services map certainly indicates this but as the current owner I can assure you its not been there in the approx 36 years of my ownership.


Properties to the southwest of mine are even higher than 297 the water would need to run up hill.

I have no recollection of any drain being installed on the adjoining properties when the ground levels were raised.

The piped water course in the adjacent properties however exists.

Please see the photos on this page there is not even a significant dip.

This feature doesn't exist on site



Note as this has been scaled from PDF the accuracy only allows for an approximate indication

Response to DCC letter regarding an open drain on 297 Tomahawk Rd.