

Automotive Solutions Otago Ltd

Robert Le Brun Automotive Solutions Ltd 57 Anzac Avenue Dunedin

DCC Roading Manager 50 The Octagon PO Box 5045 Moray Place Dunedin 9058

To Whom It May Concern:

This letter is in regards to the intersection at Anzac Avenue and Frederick Street. We own a business on this corner and have noticed the following since the recent road layout change:

- There is confusion when cars approach this intersection from Frederick Street
- The posted temporary 30km speed sign is not being observed in fact it is being totally ignored
- There are more "near misses" now than when there were no traffic lights at all

We now no longer use this road to access our business as it has become too dangerous. In our opinion the traffic lights must be turned on as soon as possible, the current situation is ridiculous and dangerous for all drivers and has gone on for much longer than necessary.

Please remedy this situation by turning on the traffic lights, as they were installed to control and direct traffic, not to confuse people.

Kind regards

Robert Le Brun Director Automotive Solutions