

APPENDIX 4

PHOTOS AND IMAGES

Photographer: Tim Read.

Camera: Nikon D5100.

Lens: 35mm fixed focal length Nikkor DX.

Tripod used with levelling bubbles for Image 7.

All photographs of the site taken on 21 January 2016.

Locations: See map below and the titles of the images.

Map 1: Section of North Road and property at 22 Cleghorn Street – The numbers on the map correspond with the image numbers and indicate the locations at which the photographs in this Appendix were taken.



Image 1: Opposite 682 North Road. Ms Barringer's home is located to the right of the red arrow



Image 1a: Crop of Image 1 – Viewing pole 1 just visible below tree line.



Image 2: Beside power pole in the corner before Cottle Street.



Image 2a: Crop of Image 2 – Neither viewing pole is visible.



Image 3: Halfway between power poles in the corner before Cottle Street.



Image 3a: Crop of Image 3 – Viewing pole 2 is visible through the trees.



Image 4: Beside power pole just before Cottle Street.




Image 4a: Crop of Image 4 – Neither viewing pole is visible.




Image 5: 10 metres before power pole on last left hand corner before the property.



Image 5a: Crop of Image 5 – Viewing pole 2 is just visible through the trees.



Image 6: Beside power pole just before last left hand corner before the property.



Image 6a: Crop of Image 6 – Viewing pole 1 is visible just above the ridge line.



Image 7: Taken from boundary with 26 Cleghorn Street looking towards Mt Cargill.

- Camera at 1.5 metres from ground level.
- Camera level with the horizontal.



Image 8: Cleghorn Street showing shade from Macrocarpa trees opposite 22 Cleghorn Street at Midday. (Date: 04-12-2015)

