



1. Top of old road (left) and new road (right), mostly within road reserve, now mostly out of scope



2. Top of old and new access ways, showing cuts. Top part within road reserve is now out of scope



3. New access way viewed from Annie St below



*4. New hairpin access to Annie St, seen from above*



*5. New Hairpin access to Annie St from below*




6. Old hairpin access to Annie St seen from southern end



7. Earthworks near electricity pole



8. Earthworks near telecommunication utility



9. Large cut shown next to person for scale (faces redacted for privacy)



*10. Stormwater diverted towards new culvert*



11. New culvert discharge point viewed from above



12. New culvert discharge point viewed from above